

C. 2682

NEWCASTLE-on-TYNE,

22nd September, 1919.

W.T. BADGER

the Ministry of Shipping survey the Electrical Installation of the S.S. "MINNA HORN" 3431 tons gross on the 9th July, 1919 and subsequently, in order to ascertain as far as possible the condition of the Electrical Installation, prior to the vessel being taken over by H.M. Government.

The undersigned in conjunction with the Owner's Representative visited this vessel on the 9th July, 1919 and made examination as far as practicable. The recommendations were made in order to place the Electrical Installation in the same condition as prior to the internment.

FOUND

Switchboard - switches loose and very dirty. all fuses damaged.

Engine Room -


Fittings loose and dirty. Portable connections damaged and flexibles faulty.

RECOMMENDED

Switches to be taken off, and refitted on their present bases. New fuses to replace those damaged.

Note: A new switchboard of British manufacture was fitted.

Fittings to overhaul and clean. New flexibles for portables to provide. New distribution box to fit.



Lloyd's Register
Foundation

W203 - 0224 1/2

.S. "MINNA HORN"

FOUND

Lights in crews quarters
bathroom and W.C's have
no lamps, globes or guards.

Navigation circuits -
fittings damaged and
flexibles useless.

Bell circuits in bad
condition, bells and batt-
eries taken away.

RECOMMENDED

To overhaul and repair
as necessary.

Fittings to overhaul and
repair and flexibles to renew.

To be rewired, new bells
and battery to be fitted.

W.T. Badger.

Surveyor to Lloyd's Register.



© 2020

Lloyd's Register
Foundation

W203 - 0224