

S.S. "PAGASITIKOS".

I telephoned Mr. Soulsby of Messrs. Runciman (London) Ltd. and explained that the only survey requirement which required early attention was the examination of the centre furnace of the port boiler. It appeared, that the letter addressed to the Owners on the 25th instant had not yet reached them, but as the position was made clear to them over the telephone, it being pointed out particularly that there was no question of drydocking as far as Lloyd's Register was concerned, that the matter is now quite understood and is in order.



*Raf*  
© 2019

26.3.42.

Lloyd's Register  
Foundation

W 205-0117

be pleased if you will kindly take this further message into consideration when replying.