

2m,742.

1

10 SEP 1942

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "PACIFIC STAR" REPORT Liv. No. 118308


For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DOCKING ~~When due~~

Subject to indented plates Nos.3 & 4

(p.s.) in 3rd strake below sheer, to stem and stem plating being repaired at the Owners' convenience and to stem plate edges being specially examined at the next dry docking.



© 2021
Lloyd's Register
Foundation

W208-0051