

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor 1 - JAN 1924VESSEL'S NAME S/L. T. S. S. OTAKIRpt. Lon. No. 87326

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

S.S. No. 1 & Alterations

Subject Indented plates in way of N° 4 hold to be
dealt with at owners convenience

The S.S. No. 1 has now been held, ~~and the following repairs~~
~~done due to wear and tear:-~~

The indented plating examined & of so slight a
nature, that in the Surveyors opinion, this
condition may be deleted from the S.R. List.

N° 1; 2 & 5 holds now insulated & a new
flat fitted over refrigerating machinery in
accordance with the approved plan. The
funnel has been dispensed with in way of this
flat in N° 4 hold & a W.T. door fitted at fore end
of N° 5 hold.

It is submitted the vessel is worthy to remain as classed, with record
of Survey 12.23 Lon and notation of S.S. Lon N° 1, 23 as recommended.
& without conditions

100 A.1.

Shelter dk. with fld.

12.23 LonS.S. Lon N° 1, 23

} without etc.



© 2021

28.12.23

Lloyd's Register
Foundation

W208-0055

Shelter dk with fld

12.11.23

FRI