

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "OTAKI"Report Gls.No. 39597For the CHIEF SHIP SURVEYOR ~~AND CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

The Downton Pump has been dispensed with for the present, but it is concluded the owners are agreeable to fit same when requested.

* 100 A.1. (steel). "Shelter Dk. with Freeboard."

2 Dks (steel) & Shelter Dk. (steel)

Cell DB 386' 1275t. FRT 125t. APT 80t.

FK 8BH to Shelter Dk. Conn. Lloyds A4CP P31' F43' on Shelter Dk.

W208-0075

Certificate written

Noted for posting

© 2021

Lloyd's Register
Foundation

12-2-20