

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

12 MAY 1942

VESSEL'S NAME "PINNA" REPORT Sng. No. 7058

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to permanent repairs being effected to indented bottom plating in No.5 D.B. tank (p.s) at the Owners' convenience and to 90 fathoms of chain cable being supplied at the earliest opportunity (and to a bower anchor and 45 fathoms of chain cable being supplied.)

The SINGAPORE Surveyor reports (1,42) a new bower anchor and 120 fathoms of chain cable supplied.

All the temporary cable which was provided has now been removed.

The vessel's equipment is now deficient by 15 fathoms of chain cable.

It is submitted the vessel appears worthy to remain as classed without fresh record of survey subject ~~to~~ indented plating as above (and to 15 fathoms of chain cable being supplied).

As now, subject etc.

Amend S.R.L. regarding equipment.



© 2021

CoA's Register
Foundation

12-5-42

W208-0086