

by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

L'S NAME "QUEENSBURY" Rpt. Sld No. 33035

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented shell plating and framing in way being dealt with at the first convenient opportunity.

The SUNDERLAND Surveyors report the vessel placed in dry dock, the bottom coated, a number of hatch covers renewed and minor repairs effected.

The indented plating, as above, continues efficient.

It is submitted the vessel appears worthy to remain as classed with record of survey 1.41, subject as as above.

100A1)
With fbd) Subject, etc.
1.41 Sld)



© 2020

Lloyd's Register
Foundation

W210-0002