

Received at London Office FEB - 3 1941

W210-00

Insert Character of Ship and Machinery precisely as in the Register Book

...a complete requirement. If so, to be sent

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.

If Stockless, state Mechanical Tests

J. Grieve © 2020
Engineer Surveyor to Lloyd's Register of Shipping

© 2020

Lloyd's Register
Foundation

W210-0004

Starboard Boiler (cont) Port safety valve lid & seat renewed & other minor repairs carried out to mountings. Front circumferential seam in way of collision chock recoiled.

Auxiliary Boiler; minor repairs carried out to mountings

NOTE:- Steering Engine cylinders renewed complete with pistons & valves. Steering engine observed when running under working conditions & found satisfactory.

It is submitted that
this vessel is eligible for
THE RECORD.

B. 141

Yours

2241