

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

25th September, 1928.

Dear Sir,

S. With reference to Greenock Report No. 18958 on the Steamer "PREDSIEDNIK KOPAJTIC", I have to say it is concluded that there are four bilge suction in the machinery space, viz:- 2 suction of $2\frac{1}{2}$ " bore on the starboard side and one of $2\frac{1}{2}$ " and a direct suction of $3\frac{1}{2}$ " on the port side, in addition to the bilge injection, but I shall be glad if you will kindly ascertain from the Surveyors, and let me know whether this is so.

I am, Dear Sir,

Yours faithfully,

Clerk to the
Classification Committee.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register
Foundation

W210-0256