



Lloyd's Register of Shipping.

Norra Hamngatan 6,

Göteborg, 30th January, 1941.

W O K I N G H A M.



The Secretary,
LONDON.

Dear Sir, m.s. "REMMAREN".

I beg to acknowledge the receipt of your telegram dated the 29th instant reading as follows:-

"YOUR REPORT 13098 STATE IF FRAMES REVERSES AND WIDTH OF BRACKETS OPEN FLOORS AS REPORTED ARE CORRECT ALSO UNSUPPORTED SPAN"

In confirming our reply as follows:-

"REMMAREN FRAMES REVERSE FRAMES AS REPORTED BUT BRACKET AT MARGIN SHOULD BE 1175 MIDSHIPS"

we think it well to add that the minimum breadth of the brackets at the margin plate is 900 mm., but that at midship the breadth is 1175 mm., thus maintaining the unsupported span as indicated on the plan of Midship Section.

I am, Dear Sir,

Yours faithfully,

S. Gonsky



© 2019

Lloyd's Register
Foundation

W211-0139

Handwritten signature

Handwritten signature

Handwritten initials

Handwritten signature

Yours faithfully,

I am, Dear Sir,

on the Dean of Windsor Section.

is 1112 mm. the measuring the unboxed above as indicated at the margin plate is 800 mm. but that at Windsor the present we think it well to say that the minimum present of the present

BECKETT AT WINDSOR SHOULD BE 1112 MARGINS.

"BETHUNEN BECKETT BECKETT BECKETT AS BECKETT BE"

IN CONFIRMING THE BECKETT AS FOLLOWS:--

UNBOXED BECKETT

OF BECKETT ONE 11002 AS BECKETT THE CORRECT ALSO

"LOAN BECKETT 12008 STATE IN BECKETT BECKETT AND WIND"

ated the 50th instant resulting as follows:--

I beg to acknowledge the receipt of your reference

W.A. "BETHUNEN."

Dear Sir,

Yours,

The Secretary,

© 2019

Lloyd's Register Foundation

Corresponding, 20th 1841.

Yours faithfully,

W.A. "BETHUNEN."