

26 NOV 1942

ved by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "ROSE CASTLE" REPORT Hfx. No. 4197

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*

The class is subject to indented shell plate G.11 (p.s.) being dealt with at the first convenient opportunity (and to a length of chain cable being supplied).

The HALIFAX N.S. Surveyors report the vessel afloat and on account of damage through heavy weather, a lifeboat renewed complete with all equipment and davits repaired.

It is submitted the vessel appears worthy to remain as classed subject as above.

As now, subject etc.

(CASUALTY).

SR
25-11-42

Lloyd's Register
Foundation

W212-0002