

Abb. F. B.T.H. Co
2 JUN 1933
Rugby

(Received at London Office.....19....)

To. Place Rugby Date 1st June 1933

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to inspect the new HP and LP rotors complete with bucket wheels, blading, and couplings now being manufactured for both S.S. "Serooskerk" and "Zuiderkerk". Fees and expenses as already agreed in your letter of the 31st May 1933.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:-

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

THE BRITISH THOMSON-HOUSTON Co. LTD

W. J. Belsey
MANAGER MARINE DEPARTMENT
per: J. R. Ganning

To the Secretary,

Lloyd's Register of Shipping,
71 Fenchurch Street, London, E.C.3.



2019
Lloyd's Register
Foundation
W 214 0137