

"SAN ERNESTO"

The Diesel Engine driving the Auxiliary Dynamo has not been constructed under survey, but is a Ruston Hornsby Engine of approved type.

There is a steam driven Electric Generating Set and all the auxiliaries to main propulsion are steam driven.

The First Entry Report is to hand and the Surveyors report all machinery satisfactory under working conditions.

IT IS SUBMITTED that as no essential service is dependent on the Diesel Electric Generating Set its construction under survey was not required by Rule, and the Owners, together with the Grimsby and Middlesbrough Surveyors, should be advised accordingly.

Lr 26/4 Ruston
S.D. *al* 13.4.39.



© 2019

Lloyd's Register
Foundation

W215-0141