


Owners: Eagle Oil & Shipping Co. Ltd.

m.s. "SAN ERNESTO" (Furness S.B. Co's Yard No.300)

3VQZ Generating Set by Ruston & Hornsby Ld.


As the above vessel is about to proceed on her trials, Mr. Williams, Superintendent of the Owners, was informed by 'phone that the Diesel Auxiliary Generating Set had not been constructed under the supervision of the Society's Surveyors (see Grimsby letter dated 22.3.39); whereupon he requested that this might be confirmed by letter, so that he could take up the matter with the Builders personally, as he will be present at the trials.

IT IS SUBMITTED that a letter be addressed to the Owners, for attention of Mr. Williams, confirming this telephonic conversation.


27.3.39.

IT IS FURTHER SUBMITTED the Grimsby Surveyors be informed that the Owners' Superintendent has no knowledge of the instructions quoted in their letter, and that the Owners are taking the matter up with the Builders.

Ld 27/3


27.3.39.

© 2019
Lloyd's Register
Foundation

WZ15-0150