


NOTES & ALTERATIONS



CHARGE TO COMPONENT No 1.

1950-51

Messrs. Richardson, Westgarth & Co., Ltd.

Engine No. 2695.

Crankshaft.

W. HPL RPT. No. 18170.

S/S "St. Essylt"

Hull Rpt.
Sld 33210



© 2021

Lloyd's Register
Foundation

W216-0112