

Class is Subject to the exhaust gas

~~DONKEY~~ BOILER

not being used again.

-6 MAR 1936

3E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

EL'S NAME

Silveray

Rpt.

Ver.

No. 4165

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/32.)

of Survey

SPECIAL SURVEY OF ENGINES AND/OR BOILERS PARTLY HELD FOR S.S. No. 3

MC

MC(M)

due

7.37

, partly held for cs.

IS

1.36

now held.

SS

now further advanced and the following repairs effected (due to heavy weather)

No 2 main bearing retapped & examined

Main wear then repair effected.

A new exhaust gas water heater fitted

It is proposed to complete the survey as occasion arises

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

here (with date) when the survey has been completed. Y.D.B. 2.36 now

CS

The following remains to be done to complete the Survey

See form 78

21.36

Without Special Condition

Y.D.B. 6.3.36

Note: The Exhaust gas heater is
not now to be recorded in RBS

See letter 17.2.36



© 2019

Lloyd's Register
Foundation

W217-0029