

COPY

M.V. "SILVERAY"

WEATHER STATEMENT

VOYAGE 24

Colombo to Penang.

Cebu (P.I.) to Los Angeles

- 15th Nov: Fresh breeze, rough sea. Rolling. Engines racing, governor working.
- 16th Nov: Fresh breeze, rough sea. Rolling. Engines Racing, governor working.
- 16th Dec: Mod. breeze & sea, v/l pitching easily. Engines racing, governor working occasionally.
- 17th Dec: Mod. breeze, sea & swell. V/l pitching. Engines racing, governor working.
- 18th Dec: Light breeze, sea & swell. V/l pitching. Engines racing, governor working occasionally.
- 19th Dec: Fresh breeze, rough sea, heavy swell. V/l pitching. Eng. racing, governor working occasionally.
- 20th Dec: Strong breeze, mod. gale, pitching & rolling to rough sea and heavy N.E. swell. Engines racing, governor working.
- 21st Dec: Fresh gale, rough sea, confused swell. V'l pitching & labouring. Eng. racing, governor working.
- 22nd Dec: Light breeze, mod. swell, engines racing, governor working occasionally.
- 23rd Dec: Light breeze, mod. swell, V/l pitching, governor working occasionally. Eng. racing.
- 25th Dec: Fresh to strong breeze, pitching to mod. sea & swell. Engines racing slightly.
- 26th Dec: Strong breeze, V/l pitching to mod. sea & heavy swell.
- 27th Dec: Mod. breeze, pitching to mod. sea & swell, engines racing slightly.
- 31st Dec: Mod. heavy breeze & sea. Rolling to mod. swell. Engines racing.
- 1st Jan: Mod. wind & sea. Rolling to mod. swell. Engines racing. Fore Peak tank, after bulkhead No.1 hold. Two seams caulked (corner stringers).
- 2nd Jan: Fresh gale. Rough sea. Mod. swell. Engines racing.
- 3rd Jan: Strong gale, pitching & labouring to very rough sea & high W.N.W. swell. Engines racing, governor working.
- 4th Jan: Fresh gale. Pitching & labouring. Rough sea. Heavy confused swell. Engines racing, governor working.
- 5th Jan: Fresh gale. Pitching & labouring to rough sea and high swell. Engines racing. Governor working. Mast head lights failed, temporary repairs effected.
- 6th Jan: Fresh to mod. breeze. Pitching to mod. swell. Engines racing, governor working.
- 7th Jan: Fresh breeze. V/l pitching to mod. sea & swell. Engines racing, governor working. 5:45 p.m. Main engine jacket water pump rod fractured flush with connecting link. Auxiliary pump running.
- 8th Jan: Light breeze, pitching to mod. swell. Engines racing, governor working.
- 9th Jan: Fresh breeze, pitching to mod. sea & swell. Engines racing. Governor working.
- 10th Jan: Strong breeze. Pitching to rough sea & swell. Engines racing, governor working.
- 11th Jan: Strong breeze. V/l pitching and rolling to rough sea & heavy swell. Engines racing. Governor working.
- 12th Jan: Strong breeze. V/l pitching & rolling to rough sea & very heavy swell. Engines racing, governor working.
- 13th Jan: Mod. breeze, pitching to mod. sea & swell. Engines racing, governor working.

(Sgd) H. Foster
Chief Engineer

(Sgd) R.G. Tilmouth
Master

W-217-0039

Lloyd's Register
Foundation