

127
COPY

SILVER LINE LTD.

M.V. "SILVERAY"

SAN FRANCISCO
20th January, 1936

Extract from Chief Officer's Log.

6:00 A.M. The lead covered wires leading from Captain's bathroom to Starboard Lamp Locker and gangway connection were found on fire in several places. Several deck planks were charred and wires were cut and disconnected in above bathroom. It was necessary to use water to extinguish burning pitch and wood of deck overhead.

(Sgd) R.G. Tilmouth

Master

(Sgd) C. Bulteel

Chief Officer



© 2019

Lloyd's Register
Foundation

W 217-0040