

MARY OF DAMAGE REPAIRS:—

Shell Plates.	Frames.	E. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
---------------	---------	------------	---------	--------	--------------	-------------	---------------

m.11.26.

t to Chief Surveyors

Received from Chief Surveyors

SSEL'S NAME *Steers. Storsten*

Report *Gr.*

No. *48013.*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

ture of Survey

Damage. Alterations When due
New Engines

Subt.

Port ridge keel to be repaired at owners convenience

W.A. 6. 28

Without other conditions



© 2019

Lloyd's Register
Foundation

W219-0156

elling Expenses in charge

ond Surveyor's Fee (if any) £

30.6.28

Surveyor to Lloyd's Register of Sh