

Report of Survey for Repairs, &c., of Engines and Boilers.

July 24 26 Glasgow
Date, First Survey July 15 26 Last Survey July 23 26
STORSTEEN
Glasgow
By whom Barclay Curle & Co. Ltd. When 1926
Boilers, when made (Main) Owners' Address Port Tonsberg Voyage
If Surveyed Afloat or in Dry Dock afloat.

Particulars of Examination and Repairs (if any) MACH. 100 A 1
Class contemplated Carrying Petroleum in bulk
Longtl. Framing
OIL ENGINE

done for damage stated to have been caused by overheating. The bottom liner of No 3 cylinder found fractured around scavenger ports, and lower cylinder cover scored together with its rings. done - A new lower cylinder liner now fitted, cylinder cover dressed where scored & set of new rings fitted. Machinery examined under full working conditions found satisfactory.

Observations, Opinion, and Recommendation:—
The above is for the information of the Committee.

GLASGOW 27 JUL 1926
Fees applied for 24/7 1926
Received by me 31.8 1926
Lloyd's Register Foundation

Damage repairs to Engines.
effected.

It is submitted that
this vessel is eligible to
remain as CLASSED.

AD
29/7/26

N.B.—If this Report is copied by copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.



© 2019

Lloyd's Register
Foundation