

Surveyors

Received from Chief Surveyors

NAME "CRAFTSMAN" Report Liv. No. 114724


For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey Damage. When due

Noted.

The class is subject to the HP astern turbine being repaired on return to the U.K.



Handwritten signature and date: 9.9.40.

W22 - 0006

Handwritten notes at the bottom of the page: "AMT inspection pipe here found fracture"