

2m.7.42.

THE 3RD S.S. No.1 BECAME DUE 2.42.

14 DEC 1942

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME S.S. "SUSANA" REPORT Phl. No. 8284

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Damage When due

Subject to the rudder arms E.W. 9.41 and 4.42 being specially examined at the next dry docking and to indented shell plates B1 & 2, D1 & F1 (p.s.) and B.2, D.1 & 2 (s.s.) with structure in way being specially examined at the next dry docking and dealt with at the first convenient opportunity.

Wab
9.12.42

© 2019

Lloyd's Register Foundation
W220-0002

Macb

Minutes