

COPY.

# Lloyd's Register of Shipping.



Port PHILADELPHIA, PA.

5th October, 1942

**This is to Certify** that

W. H. RUNHAM

the undersigned Surveyor to this Society did at the request of the Owner's Representative, attend on board the steel screw steamer "SUSANA", 5929 tons gross register of Manila, P.I., to survey and ascertain the nature and extent of damage stated to have been sustained through collision while in convoy on September 3, 1942.

For further particulars, see vessel's Log Book.

On September 17th, 1942, the vessel then lying afloat at Pier 46, North, the undersigned made examination and -

FOUND

No. 2 port lifeboat damaged beyond repair.

RECOMMENDED

Lifeboat to be renewed.

A new lifeboat has now been placed on board.

*W. H. Runham*  
Surveyor to Lloyd's Register  
of Shipping

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."