

2

12 JUN 1940

Sent to Chief Surveyors 8.6.40

Received from Chief Surveyors

VESSEL'S NAME

Terrani

Report

Hl

No. 50611

**For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

S.S. No. 2 due 11, 38 PARTLY HELD.

When proposed to be completed


TO COMPLETE THE M.S. ELECTRICAL INSTALLATION  
TO BE MESSER TESTED.

1st S.S. No.2 due 11.38 has been completed with the exception of the examination of the cross and wing bunkers. X

The year of grace which was granted, expired at the end of November last and when the case last received consideration in April, action was deferred for a short time.

In reply to inquiry the Hull Surveyor writes that the vessel is still away fishing and the Owners will endeavour to complete the survey on the vessel's return as opportunity offers.

It is submitted for consideration whether action might be deferred for a short time.




© 2020

Lloyd's Register  
Foundation

11.6.40

W221-0004

Vess

epor  
earn  
ntic  
peci  
tten

1811

2000

you are given and situation is unusual unusual

you are

you are

1811

you

1811

1811

1811

1811



© 2020

Lloyd's Register  
Foundation