

COPY

Lloyd's Register of Shipping.



Port

BOMBAY.

28th AUGUST 1942.

This is to Certify that I have

Surveyed the Steel Screw Steamer "TILAWA" 10006 tons gross of Glasgow, as she lay afloat and in Hughes Drydock, Bombay for damage due to vessel grounding at Killindini

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, ~~stating that all repairs recommended by me have been completed to my satisfaction~~ and that I have Recommended that she be continued in her present class viz: ~~100 A1~~ with freeboard with fresh record of Survey Bom. 7. '42 subject to permanent repairs to stem and bow plating and to permanent repairs to after keel (trough) plate at the first opportunity

being fit to carry dry and perishable cargo.

H. Southwell

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."