









"TACOMA STAR"

(cont'd) Since writing the above report the following survey has been held.

Damage stated to have been sustained through contact with Canada lock wall, Liverpool, whilst entering docks on 30th October 1941.

Vessel afloat.

Examined starboard shell plating aft of poop spaces in way & found No 2 plate from aft in main sheerstrake set in sharply & 2 frames & beam knees affected.

TEMPORARY REPAIRS:- Riveting, caulking & portlights overhauled as necessary.

It is submitted that permanent repairs to No 2 main sheerstrake plate etc, (s.s.a.) be effected at Owners convenience.

W.A.R.