

# Lloyd's Register of Shipping,

5, Alexandra Buildings,

Hong kong May 27th. 1927.

*Ans  
28/6/27*  
Secretary,  
London.

Dear Sir,

Referring to Hong Kong Report No. 6136 on the S. S. "MILBOET", I am forwarding under separate cover plans showing arrangement of shift of butts in shell, tank top, and deck relating to join new fore end to old aft end.

These are all original butts and no new butts are being used, but I shall be glad to be informed by cable if additional compensation will be required at the junction of new and old material, i.e. at the junction of the new fore end to old aft end of the vessel, as I understand additional compensation has been effected in similar cases, but possibly in a much older ship.

This vessel is about ten years old and the after end, aside of damage, is in excellent condition and in my opinion additional compensation at the junction should not be necessary in this case.

I enclose some photographs which may be of interest.

I am, Dear Sir,

Yours faithfully,

*See attached  
bag.*© 2019  
Lloyd's Register  
Foundation



Referred to the Chief ~~Ship~~ Surveyor.

am

27 JUN 1927

Also for Mr. S. A. Hill to note.

Also for Mr. Hill to note.

WIRE REQUESTED



© 2019

Lloyd's Register  
Foundation