

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C. 3.

11th October, 1918.

Dear Sirs,

With reference to the First Entry Report No. 10622^a on the Steel Screw Steamer "TJILECOEL", I have to state that before this case receives consideration, you should state whether you are correct in reporting the thickness of the tank top plating in the Engine space as .44.

You should also forward a sketch showing the positions of the side girders and of the manholes fitted in the double bottom floors.

I am, Dear Sirs,

Yours faithfully,

Secretary.

The Surveyors,

ROTTERDAM.



© 2019

Lloyd's Register
Foundation

W223-0174