

- 4 NOV 1941

ived by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

WAR MEHTAR

Rpt.

Nwc

No. 99855

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd S.S. No. 2 became due 10.40.

The NEWCASTLE Surveyors report the vessel placed in dry dock, bottom coated, and on account of damage during fuelling operations and through cause not stated, repairs effected to side house and deck fittings, and the foremast and rigging repaired.

A General Examination has been made, riveting and caulking overhauled, repairs to decks, etc. carried out.

Some alterations have been carried out in connection with gunners' accommodation.

The Surveyors recommend a notation of 'Examined 10.41', valid for 12 months, be assigned.

It is submitted action be deferred and this recommendation concurred in.

Insert in S.R.L: Exd. 10.41 (12 mos)

(DOCKING DATE 10.41)

W228-0006

