

W228-0151

nt to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

M. S. Vikingstar

Report

Liv

No.

86549

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

No.

SURVEY PARTLY HELD.

3. 24

When proposed to be completed

en due

ion of Survey held, &amp;c.,

To complete survey see report

Subt. Belin plates (E.W. repair) to be specially  
examined at next P. Working. Gutter angle to  
connect to tank top

Amend record of Deck to  
3 Sts (SR) & Stiller M (SR)

11.3.24