

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl Ss AARO* Rpt. *Cpr* No. *7120*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

*1<sup>st</sup> Long*  
Transverse No. *4360*Depth "d" *14.756 M.D*Framing: Table No. *'*Description *Built angle frame as approved.**2<sup>nd</sup>* Longitudinal No. *13829*Proportions Length *14.23 to M.D*  
Depth = *11.59 to Q.D*Deck Sheerstrake *as approved.*

Revised Rules

This vessel appears to have been built in accordance with the *Revised* Rules and the approved plans, and it is submitted she is eligible to be classed

+ 100 A.1. (Steel)

1 dk (Stl) well dk

Cell D.B 210' 40" , F.P.T. 32t, A.P.T. 86t.

F.K. 4 B.H. Cam, Rlyds A+CP.

P 17' , Q 76' , B 96' , F 28'.

It should be pointed out to the ~~Surveyor~~ that in future similar cases they should state in their General Declaration whether the Deckboard has been verified and cut in on the vessels side.