

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

BRAGANZA

Report

N.Y.

No. 39953

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

Condition

When due

—

Subject to shell plate no 2 in 5<sup>th</sup> strake below sheer (ss)  
(slightly indented & cracked) being permanently repaired  
at the owner's convenience

AES  
18.3.60

Delete from SPL— Dry docking



© 2019

Lloyd's Register  
Foundation

W234-0006