

Is an approved appliance fitted at the after

the shaft now fitted new?

Has it a continuous liner?

m/v. "Pacific Trader"

Sld. Rpt. 28810.

It is submitted that
this vessel is eligible for

THE RECORD. + LMC 5. 24. CL.

Oil Engines. 2SC. SA.

4 Cy $22\frac{13}{16}$ " - $9\frac{1}{4}$ " 2 DB 125Hb. 498 NHP.

by New York

W2
20/5/24

W234-0046

© 2019

Lloyd's Register
Foundation