



Lloyd's Register of Shipping,

97 & 98, Scottish Provident Buildings,
Donegall Square West,

Belfast, 23rd December, 1931.

Reference

The Secretary,
LONDON.



Dear Sir,

With reference to Belfast Report No.10,739 on the M.V. "CORBIS", it is regretted that owing to a clerical error the diameter of the rudder main piece at the head is given as $9\frac{3}{4}$ ". The correct dimensions are as follows:-

Diameter at head 13"

" " heel $9\frac{3}{4}$ "

I am, Dear Sir,

Yours faithfully,

Jas. J. Rennie



© 2019

Lloyd's Register
Foundation

W235-0006

Referred to the Chief Ship Surveyor

CHB

24 DEC 1931

Also for Mr. S. A. Hill to note

[Signature]

[Signature]



© 2019

Lloyd's Register
Foundation