

Clean is Subject to main inlet Sea chest  
being permanently repaired at Gls.

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME

City of Venice

Report

Gls

No. 56532

**For the CHIEF SURVEYOR and CHIEF ENGINEER SURVEYOR.**

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - (Extract from Sub-Committee's Report, 24/5/02.)

Survey

Damage repair & alteration When due  
to Steam pipe line

Noted

4  
Jan

3.2.36

Subject to main inlet Sea chest  
being renewed at owners convenience



© 2020

Lloyd's Register  
Foundation

W236-0009

30 lbs per sq" hydraulic pressure and found good. This has been put