


M.V. "CONGELLA"

On the 27th ultimo the Falmouth Surveyors were requested to explain why the usual method of drawing up a Special Damage Report was not followed in the case of the above vessel.

In reply they state they regret that the nature of the damage was not stated clearly in their report, and they furnish an explanation as to the reason for renewal of rivets, ceiling etc.

As the fees appear to be unpaid it is presumed that this report has not been issued, and it is submitted that the Surveyors be instructed to rewrite this report, drafting it in the usual manner.


4.3.35



© 2019

Lloyd's Register
Foundation

W238-0152