

s.s. "THEMONI".

It is submitted the Hull Surveyors be informed that no particulars of the masts of this vessel are available in this Office.

Their attention should, however, be drawn to Section 37, Paragraph 6(b) of the Rules, and it should be pointed out that the responsibility for the suitability of the mast and the staying of the same ^{for the loads to be carried as stated in their letter} must rest between the Builders, or Repairers, and the Owners.

*Dr. 9/8/33
and 10th,*

SA
10. 8. 33.



© 2019

Lloyd's Register
Foundation

W239-0051