

Acas Paid.

to Chief Surveyors

Received from Chief Surveyors

SEL'S NAME

Steel Twin Sc.S.S. "EL MADINA"

Report

Gls.

No. 59070

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

When due

100AL

2 Dks.

Cell.DB 295' 609t, DTa 26' 316t, DTf 12' 205t, FPT 52t, APT 60t.

FK, 6BH, cem., Lloyd's A & CP.

Shade dk., F. on Shade dk. 44'

O.L. 374' - 5 $\frac{1}{4}$ ".



© 2020
3.12.31

Lloyd's Register
Foundation

W240-0099