

LLOYD'S REGISTER  
RECEIVED  
30 DEC 1936  
ADD. 30  
LONDON

OUR REF: 9275M.

(Received at London Office )

# REQUEST FOR INSPECTION SERVICES.

DATE 29th December, 1936.

We confirm our request to the Committee of Lloyd's Register, that they will instruct the Society's Surveyors to inspect Superheater Apparatus for Messrs. Barclay, Curle & Co.'s Engines No. 666, Yard No. 666.

at The Superheater Co., Ltd., Mosley Road, Trafford Park, Manchester, 17.

and we agree to pay the ~~fees and expenses~~ inclusive charge of £4. 4. 0. incurred for these services.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”


NAME OF FIRM The Superheater Co., Ltd.,

ADDRESS Bush House, Aldwych,

LONDON, W.C.2.

After signature, please return this form to:

THE SECRETARY,  
LLOYD'S REGISTER OF SHIPPING,  
71, FENCHURCH STREET,  
LONDON, E.C.3.



Lloyd's Register  
Foundation  
W240-0193

*Referred to the Chief Engineer Surveyor*

*H/B*

30 DEC 1936

*al*



© 2020

Lloyd's Register  
Foundation