

~~WRECK~~ REPORT OF TOTAL LOSS, CASUALTY, &c.

Box 241

No. 22695 in R.B. Wreck Book, p. 79/44.

Date of writing this report

19

Vessel's Name *S.S. Don Ricardo* \* of Valparaiso

Tons Gross 2629  
Net 1653

Built at *Hull* When 1906 12 Casualty notice sent to Owner

Owner's reply

Owner's Name *Compañía Carbonifera e Industrial de Lota*  
Address *Casilla 145 V, Valparaiso, Chile.*

Case previously before Classing Committee. Date

Particulars of Classification.	
+ 100A1	+ 2MC 7.3
3.42	
SS No 3-	SS 7.43
" 34	
SS No 1-38	TS 342CA

Date of Casualty *9th May, 1944.*

Précis of particulars of Casualty While the Chilean steamer

"DON THOMPSON" was towing the Chilean steamer

"DON RICARDO" out of Caleta Chambique, slightly north of Lota, the "DON THOMPSON" was unable to control her tow owing to the strong current. To avoid the current taking the "DON THOMPSON" on to the rocky reef that runs out from Pique Alberto Point the "DON THOMPSON" threw off the tow rope and the "DON RICARDO" drifted on to the reef on the 9th May, 1944.

Subsequently a storm broke the hull and carried the forward half seawards, completely submerging it.

Stated no hope whatever of refloating the vessel.

SOURCE OF INFORMATION.

MARINE CASUALTIES

*DON RICARDO*.—Concepcion, May 9.—Chilean steamer Don Ricardo is ashore about 10 ft. off Lota Bay, settled on rocky reef in exposed position hundred yards from shore. Nos. 2 and 5 holds taking water, bulkheads amidships buckling gradually as tide varies.

Concepcion, May 10.—Chilean steamer Don Ricardo now firmly embedded amidships on reef of rocks and main deck starting to crack.

LL 12/5

3/4

*DON RICARDO*.—Concepcion, May 12.—Chilean steamer Don Ricardo is resting on firm rock. About 10 ft. amidships bottom and double bottom buckled as also transversal bunker bulkheads. No chance of refloating owing to want of suitable salvage gear. Recommend endeavour arrange salve winches, anchors and chains and other removable gear, &c., with owners, who are in position to start work immediately, otherwise ask for tenders, but this would mean delay, and meanwhile ship might break in two if weather stormy. —Lloyd's Agents per Salvage Association.

*RICARDO*.—Concepcion, May 16.—Steamer Don Ricardo, Lloyd's Register Surveyor at Talcahuano has inspected possibility of refloating with suitable jammers and mooring wires which seemable. Present position impedes even examination of outer bunkers and sides where great damage. —Lloyd's Agents per Salvage Association.

LL 15/5

*DON RICARDO*.—Concepcion, Chile, May 20.—Steamer Don Ricardo, having recently been broken in two by a storm, has broken and carried forward half seawards, completely submerging it. —Lloyd's Agents per Salvage Association.

LL 31/5

*DON RICARDO*.—Concepcion, Chile, May 20.—Steamer Don Ricardo, having recently been broken in two by a storm, has broken and carried forward half seawards, completely submerging it. —Lloyd's Agents per Salvage Association.

LL 1/6

Suggested Record

Date of Committee

19 JUN 1944

Committee's Minute

OMR = FROM A.R.

3m.1.43.

W241-0099



© 2019

Lloyd's Register  
Foundation