

Received by Chief Ship Surveyor *28/12/06*

*Unrepaired (1st)* *Don Ricardo* **F.E.**  
Received from Chief Ship Surveyor

VESSEL'S NAME *S/S L. Lebu*

Rpt. *Jul* No. *18586*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

CLASSIFICATION.

| Items.  | Additions (if any) required by Rules, or as approved. | On account of:—    |
|---|---|--------------------|
| Main Sheerstrake . .  | <i>3/20"</i>  | <i>Provisional</i> |
| Spar Sheerstrake . .  |   |                    |
| Description of Framing:— <i>Deep (Bulb angle) framing, 1" less in depth but compensated by longitudinal &amp; partial transverse bulkheads in way of bulkheads.</i> |   |                    |

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+100A1 (Stat) as recommended.*

*+100A1 (Stat)  
2<sup>nd</sup> (Stat) & dup. framing  
N.B. = 64 DB a 88 u 24 B 40' f 166 536L APT 13L  
F.N. S.B.A., Cum, Lloyd's A.K.C. P 15, B 75, F 39*

