

COPY COPY FOR LONDON

Lloyd's Register of Shipping.



Port MONTREAL, CAN.

July 11th, 1944.

This is to Certify that

B. HARDY

the undersigned Surveyor to this Society did at the request of

The OWNER'S REPRESENTATIVE survey the steel single screw steamer "ELIZABETH DALP", 4258 tons gross register of London, while afloat at Shed 16, Montreal, P.Q., for the purpose of ascertaining the nature and extent of damage stated to have been sustained through encountering heavy weather on 13th June, 1944, while on voyage from Glasgow to Sydney, C.B.

For further particulars see Official Log Book and Protest.

FOUND

Hand Steering Gear on poop deck to have left and right handed screw bent. Both Guide Rods badly bent and Bearing Bracket on Tiller crosshead broken.

RECOMMENDED

Left and right handed screw be straightened. Renew guide screws. Renew cast iron bearing bracket on Tiller crosshead.

The repair was later examined under working conditions.

B. Hardy
SURVEYOR TO LLOYD'S REGISTER

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."