

250,110.

W Sect. 324

Bungabuh Dal

F.E.

Received by Chief Ship Surveyor 24/3/10.

Received from Chief Ship Surveyor

VESSEL'S NAME *Stl 5 5 "Maresfield"*

Rpt. *Sld.*

No. *24383.*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/02.)

Transverse No. *7941*

Depth "d" *24.96*

Framing: Table No. *3. pag 16.*

Description *Bull angle framing as approved.*

Longitudinal No. *28984*

Proportions Length = *10.31*
Depth

Bridge Deck Sheerstrake and side plating in one plate, thickness as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **✦ 100A1 ("Steel")** as recommended.

✦ 100A1 ("Steel")

1 Dr (stl.)

WB = cell DB a 125' v EB 43' f 151' 992L. F.P.T 87L. A.P.T 130L.

FK. 6BH. Lem. Lloyd's A.V.C.P. P 23' B. 234' F 31'

W Sect. 324

AP
RA
24/3/10



© 2019

Lloyd's Register Foundation

W241-0194