

S.S. "EMPIRE MOORHEN"

The Boiler Survey, due 4,43 and partly held 5,43, completed. The centre furnace of the port boiler is distorted and the Hull Surveyors state that it is efficient for the voyage to U.S.A. at the reduced pressure of 200 lb.

The electrical equipment has been ^{repaired} ~~inspected~~ and minor repairs effected.

IT IS SUBMITTED the vessel is eligible to remain as classed with fresh record of BS 5,43, subject to the centre furnace of the port boiler being dealt with, the 1st reduction pinion and wheels renewed and the remainder of the gearing and turbine bearing examined and the alignment checked on arrival at a U.S.A. port within three months.

For R.B. Pressure 200 lb.

[Signature]
20.12.43.

13/1/44



© 2020

Lloyd's Register
Foundation

W242-0020

teeth hurried over especially on the forward helix where
all left-hand helix had previously been taking the