

V.

20 APR 1944

ved by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

SEL'S NAME "FORT YALE" REPORT Hul. No. 52378

remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to indented soft nosed stem and stem plating etc. being dealt with at the Owners' convenience and to (a bower anchor and 45 fathoms of chain cable being supplied and 2 bower anchors and a stream anchor on board being submitted to the Statutory Test).

The HULL Surveyors report this vessel placed in dry dock, bottom coated.

The items, as above, continue efficient.

IT IS SUBMITTED the vessel is worthy to remain as classed with record of docking survey 4.44 subject as above.

4.44 Hul. subject.

*GA* J.F.  
13.4.44



© 2019

Lloyd's Register  
Foundation

W 244-0109

Eligible in my opinion to remain as classed with fresh record of survey 4.44. su