

s/s "Gharinda".

Cal 6046.

It is submitted that the Calcutta Surveyor
be informed it is concluded that two main
bearing bolts & one set of feed & bilge pumps
are on board as spare gear, but he should
state if this is so.

for 12/11/26



© 2019

Lloyd's Register
Foundation

W245-0112