

For the information of Surveyors and the Committee only.

Received at

Office

19

Lloyd's Register of Shipping.

: 14835.

(Report on Vessel No. 16855

Port

Hamburg)

SHIP FORGINGS OR CASTINGS.

I have to report that the undermentioned ~~XXXXXX~~ Steel ~~XXXXXX~~
ings, manufactured by Messrs. Rombacher Hüttenwerke
Bochum for the Vessel No. 93-95, being built
Messrs. Deutsche Werft A.G. of Hamburg
been inspected by me as set forth below and found to be, so far as can
en, 2 Propeller brackets sound and free from surface defects.-

ings or Castings.

17/18.

Düsseldorf 19th September 1925.

17.9.25.

1 propeller bracket

1 propeller bracket

~~XXXXXX~~~~XXXXXX~~

STEM.

17
Annealed Siemens Martin Cast Steel

18

cast

cast

Inspection ... rough turned

rough turned

Inspected ... 17.9.25.

17.9.25.

TINGS.

Standard Test
Pieces.

.798

3"

.798

3"

square inch

29,4

26,7

29,0

28,3

per cent. ...

31,6

32,9

29,0

29,0

ing Test—

120 degr. good

120 degr. good

fore fracture

rom ground ...

10 feet

10 feet

ing Test—

according to Rules

und satisfactory ...

satisfactory

satisfactory

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

(if any chargeable) £

To be paid at Düsseldorf.

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

State if annealed.