

Manchester Report No. 8084 - Remell Newbury Ing. 3143

This engine has been fitted to a common bedplate taking a Lawrence Scott generator, a ballast pump and the auxiliary air compressor. It has been dispatched to Greenock for fitting onboard Gen. Brown No. 188

Gal 10/3/34

See don't report No. 104037 on
replace engine



© 2019

Lloyd's Register
Foundation

W246-0136

The Automatic Governor been tested and found efficient when the whole load is suddenly thrown on or off

rators, do they comply with the requirements regarding rating

are they concerned around