

S. S. "KUMANOVO."

Split Rp. 509.

The dynamo cables are of lower capacity than the dynamo output but are sufficient for the connected load.

The cables might be accepted in this instance but in the event of further circuits being installed at a later date they should be reviewed.

Leow.

5/8/36

W248-0159