

STEAMER "KUMANOVO".

Before this/^{case}receives consideration IT IS
SUBMITTED the Surveyor be requested to verify the size of the
main cable to the 30 Kw. dynamo, it being noted that whilst
the cable is large enough for the current for the various
circuits detailed in the report, it is much too small for the
rated output of the dynamo.

The Surveyor should state the total load
it is possible to put on the dynamo.

R. I. L.

8th July, 1936.



© 2019

Lloyd's Register
Foundation

W248-0163